IOWA DEPARTMENT OF ENVIRONMENTAL QUALITY

A port Of Investigation

Page 1 01 1

INVESTIGATION DATE

Current July 29, 1981 |Last

TO: (Facility Name, Location & Address)

Chuck Englebert

Norplex Division, UOP Inc.

Box 445

Postville, Iowa 52162

RE:(Specify Investigation Purpose Or Cite Rule)

Hazardous Waste Inspection IAD-073489288

(Use Stamp)

FROMA: DEPT. OF ENVIRONMENTAL QUALITY REGION NO. 1

209 NORTH FRANKLIN

MANCHESTER, IOWA 52057 PHONE 319/927-2640

Persons Contacted (Name & Position)

Chuck Englebert, Plant Manager

George Stunyo, Envir. Programs

Hal Fenger, Former Plant Manager

Polk Burleson, Supt., Engrg. & Maintenance

OBSERVATIONS/RECOMMENDATIONS

Norplex Division's plant in Postville, Iowa, is in the business of manufacturing industrial thermosetting plastic laminates. Raw products are mixed and run through heat treaters resulting in a product which is then sanded and cut to finished size. Most of the waste material generated by this process comes off of the head end of the heat treaters where the raw products are first mixed. When enough waste material has collected in the mixing vessels, the wastes are pumped into 55-gallon drums and then stored outside the plant in a hazardous waste storage area.

During this inspection, I examined the facility's hazardous waste management and contingency plan. Some deficiencies were found in the plan covering Waste Analysis, Security, and Inspection. These three areas were being covered by the facility; however, sufficient documentation of how they were handled was not on hand. After discussing these three areas with Mr. Englebert and Mr. Stunyo, management plans were written up to cover them and placed in the management plan book before the inspection was completed. No other deficiencies were noted with the plans.

During inspection of the hazardous waste storage area, only one problem was noted. area lacks a dike or berm to contain spilled materials. This problem was discussed with Mr. Englebert and Mr. Stunyo at the site, and it was decided that a dike capable of containing 10% of the maximum volume that can possibly be stored in this area will be built as soon as possible. Mr. Englebert agreed to notify me in writing when this job is completed. No other deficiencies were noted during this inspection.

I would like to thank Mr. Englebert and Mr. Stunyo for their cooperation during this inspection.

> R00330118 RCRA RECORDS CENTER

Date Signature SUSPENSE DATE Inspector Joe P. Sanfilippo Regional Administrator Jerry L. Rattenborg, P.E. Enclosures (Specify) Date Copy Mailed: 7-31-81 Distribution: Regional Office: Central Office: Inspected Facility

111-

Company Name Norplex Division Date of InspectionJuly 29, 1981	1AD 0 7	3 4 8 9 2 8 8
HAZARDOUS WASTE MANAGEMENT FACILITY General Administrative Requirements Site inspection Report	2	Instruction Answer and Explain as Necessary
1. Waste Analysis (265.13) a. Waste Analysis Plan Adequate X Inadequate b. Waste Analysis Results (operating record) Adequate X Inadequate		•
2. Security (265.14) [if applicable] a. Access Control Adequate X Inadequate b. Warning Signs Adequate X Inadequate		.,
3. Inspection (265.15) a. Inspection Schedule Adequate X Inadequate b. Inspection Log (operating record) Adequate X Inadequate	2	
4. Personnel Training (265.16) a. Position Descriptions Adequate X Inadequate b. Training Records Adequate X Inadequate		
5. Preparedness and Prevention Plan (265.30) a. Maintenance and Operation of Facility (265.31) Adequate X Inadequate b. Required Equipment (265.32) Adequate X Inadequate c. Testing and Maintenance of Equipment (265.33) Adequate X Inadequate d. Access to Communications or Alarm Systems (265.34) Adequate X Inadequate e. Required Aisle Space (265.35) Adequate X Inadequate f. Arrangements with Local Authorities (265.37) Adequate X Inadequate		
6. Emergency Procedures (265.56) a. Contingency Plan (265.52) Adequate X Inadequate b. Instruction on Contingency Plan (training records) Adequate X Inadequate c. Summary and Details of Implementation of Contingency Plan Adequate X Inadequate		
7. Waste Accountability a. Manifests - HW Received & Shipped (276.71 & 262.23) Adequate X Inadequate b. Description & Location of HW within Facility (operating record) (265.7) Adequate X Inadequate	73)	

8. Groundwater Monitoring (Landfill, Land Treatment & Surface impoundment)	
a. Groundwater Monitoring Program or Alternate Monitoring Program (265.90)	
Adequate Inadequate	
b. Groundwater Sampling & Analysis Plan (265.92)	
Adequate Inadequate N/A	
c. Outline of Groundwater Quality Assessment Program (265.93)	
Adequate Inadequate	
d. Groundwater Monitoring Results (265.94)	
Adequate Inadequate 1	
e. (If Applicable) Documentation for Walver of Groundwater Monitoring (265.90)	
Adequate Inadequate	
(265 278)	
9. Unsaturated Zone (Zone of Aeration) Monitoring Plan (Land Treatment Facility) (265.278)	
a. Plan	
Adequate Inadequate	
b. Monitoring Results N/A	
Adequate Inadequate	
10. Closure	
a. Closure Plan (265.112)	
Adequate X Inadequate 1	į
b. Closure Cost Estimate (265.142) Adequate X Inadequate	
Adequate X Inadequate cosure (265.143- by 7/13/81)	
	1
I Administrative I I madaging to I I	
Adequate N/A	
THE TOTAL PARTY OF THE PARTY OF	
11. Post-Closure (Disposal Facility)	
11. Post-Closure (Disposal Facility) a. Post-Closure Plan (265.118) Adequate Inadequate	
11. Post-Closure (Disposal Facility) a. Post-Closure Plan (265.118) Adequate Inadequate	
11. Post-Closure (Disposal Facility) a. Post-Closure Plan (265.118) Adequate Inadequate N/A Adequate Inadequate N/A	
11. Post-Closure (Disposal Facility) a. Post-Closure Plan (265.118) Adequate Inadequate N/A Adequate Inadequate N/A	
11. Post-Closure (Disposal Facility) a. Post-Closure Plan (265.118) Adequate Inadequate N/A b. Post-Closure Cost Estimate (265.144)	
11. Post-Closure (Disposal Facility) a. Post-Closure Plan (265.118) Adequate Inadequate b. Post-Closure Cost Estimate (265.144) Adequate Inadequate c. Financial assurrance for post closure monitoring & maintenance (265.145-by 7/13/81) Adequate Inadequate	
11. Post-Closure (Disposal Facility) a. Post-Closure Plan (265.118) Adequate Inadequate b. Post-Closure Cost Estimate (265.144) Adequate Inadequate c. Financial assurrance for post closure monitoring & maintenance (265.145-by 7/13/81)	
11. Post-Closure (Disposal Facility) a. Post-Closure Plan (265.118) Adequate Inadequate b. Post-Closure Cost Estimate (265.144) Adequate Inadequate c. Financial assurrance for post closure monitoring & maintenance (265.145-by 7/13/81) Adequate Inadequate	

mac/AQ2 - HWMF2

	Norplex Division	DATE OF INSPECTION _	7-29-81	1 AD 0 7	3 4 8 9 2 8 8
OMPANY NAME					INSTRUCTION
	STORAGE FACILIT	TES SITE INSPECTION REPORT	T		Answer and Explain as Necessary.
	on of Container (265.171)				
	quate Inadequate				
	ent of Containers (265.173)				
• •	lons (265,174)		,		
	quate I nadequate				
D. Special	Requirements for ignitable	Waste (265.176)			
Ade	equate Inadequate X	Not Required			
E. Special	Requirements for Incompati equate Inadequate X	Not Required			<u> </u>
F. Securi	ty				
10 9	lequate Inadequate				
	ed Emergency Response Equipm				
	Inment (264.175)	-			
1	dequate X				
1. Estim	ated Type and Number of Cont	alners			
	5 55-gallon drums	71 72 34			
1	Ing/Marking on Containers 26	۳ ۷ و کار و ا			
X A	Adequate Inadequate				

MO6

JOHN VEDDER



iowa department of environmental quality

reply to:

Jerry L. Rattenborg - R.O. #1

phone:

319-927-2640

File Name Norplex Division/ Hw Facilities

July 31, 1981

Senders Initials

Chuck Englebert, Plant Manager Norplex Division, UOP Inc. Box 445 Postville, Iowa 52162

RE: Hazardous Waste Inspection

IAD - 073489288

Enclosed you will find a copy of the hazardous waste inspection report completed by this office. It is believed the report is self-explanatory. However, should you have any questions, do not hesitate to write or call.

Since this is a relatively new program, the Central Office of DEQ may have some additional comments to forward to you upon their review of this report.

Sincerely yours,

Jerry L. Rattenborg, P.E.

Regional Administrator

JLR:mc Enc.

cc: DEQ - Des Moines

EPA - 324 E. 11th St., Kansas City, Missouri 64106

RECEIVED W.81